

Datalink Deployment Actions (post DSG10):

DEPLOYMENT ACTIONS ON ANSPs – DLS IR (29/2009): 3 actions

Action No	Who	Description	Due date	Status/Comments
DSG7 Deployment Action 12	HCAA-Greece	HCAA to offer datalink services in accordance to DLS IR (29/2009) and IR 30/2009.		DSG10: No update
DSG7 Deployment Action 14	MATS-Malta	MATS to offer datalink services in accordance to DLS IR (29/2009) and IR 30/2009.	31/Mar/23	DSG10: Testing ongoing, start of operational services delayed to 31 Mar 2023.
DSG7 Deployment Action 15	Avinor-Norway	Avinor to offer datalink services in accordance to DLS IR (29/2009) and IR 30/2009.	30/Apr/24	

DEPLOYMENT ACTIONS ON ANSPs – LOF/NAN (30/2009): 10 actions (3 inactive)

Action No	Who	Description	Due date	Status/Comments
DSG7 Deployment Action 1	NATS	NATS to operationally deploy LOF and NAN in accordance with DLS IR 30/2009 on all remaining links that support DLS	01/Jan/25	DSG10: No testing with Reims since new system in Reims (April 2022). Cannot connect to Shannon until 2025 (new centre is needed). No plan with Denmark.
DSG7 Deployment Action 2	IAA-Ireland	IAA to operationally deploy LOF/NAN services in accordance to IR 30/2009.	30/Sep/23	DSG10: LOF testing between Shannon and Brest scheduled early May 2023, if testing is OK, implementation shortly after. Shannon London no date for deployment scheduled.
DSG7 Deployment Action 3	AustroControl	Austro Control to operationally deploy LOF and NAN in accordance with DLS IR 30/2009 on all remaining links that support DLS	31/Jan/23	DSG10: Awaiting Bratislava to be ready. No active action for Austrocontrol.
DSG7 Deployment Action 4	CroatiaControl	Croatia Control to operationally deploy LOF and NAN in accordance with DLS IR 30/2009 on all remaining links that support DLS	30/Dec/22	Post DSG10: ZAGREB-BRINDISI not operational, Delayed to 2023.
DSG7 Deployment Action 5	DSNA	DSNA to operationally deploy LOF and NAN in accordance with DLS IR 30/2009 on all remaining links between centers that support DLS	31/Oct/23	DSG10: Reims-MUAC/Paris planned to be put back into ops in April (new version of 4FLIGHT). Reims-London: contacts to be taken with NATS to plan tests, probably post-summer 23 (TBC). Brest-Shannon: awaiting Shannon to be ready. Due date moved to 10/23
DSG7 Deployment Action 6	ENAV	ENAV to operationally deploy LOF and NAN in accordance with DLS IR 30/2009 on all remaining links that support DLS	10/Mar/23	DSG10: Padova LOF/NAN fix DONE.

Action No	Who	Description	Due date	Status/Comments
				Post DSG10: Only link Brindisi to Zagreb remains. Awaiting Zagreb to be ready. No active action for ENAV.
DSG7 Deployment Action 8	PANSA	PANSA to operationally deploy LOF and NAN in accordance with DLS IR 30/2009 on all remaining links that support DLS	31/Dec/23	DSG10: Warszawa-Malmo DONE, Warszawa-Vilnius delayed by software issue.
DSG7 Deployment Action 11	NAV-Portugal	NAV Portugal to operationally deploy LOF and NAN in accordance with DLS IR 30/2009 on all links between centres that support DLS.	01/Jun/23	DSG10: Delayed to Q2 2023, Will be coordinated with ENAIRE
DSG9 Deployment Action 7	LPS-Slovakia	LPS to operationally deploy LOF and NAN in accordance with DLS IR 30/2009 on all links between centers that support DLS	01/Apr/23	DSG10: LOF/NAN testing with Vienna completed, expected to go live 20Apr2023. Warsaw delayed by an issue, but still planned for spring 2023. Links to Prague & Budapest centres now done.
DSG10 Deployment Action 2	MATS-Malta	MATS to operationally deploy LOF/NAN services in accordance to IR 30/2009.		Post DSG 10: Start of DLS is delayed to June 2023 (date tbc) Action not active yet.

DEPLOYMENT ACTIONS ON ANSPs – OTHER: 15 Actions

Action No	Who	Description	Due date	Status/Comments
DSG4 Deployment Action 7	DSNA	Address CRO-773 PR (coordination capability between voice and CPDLC sessions) with the rolling out of the ER ATM system due in Q2 2022. Following coordination with DSNA, it is noted that and current procedure even if not optimal, is compliant with ED110B. The implementation of the new ATM system will address this and the termination of the CPDLC session will be with the controller input.	30/Jun/22	DSG10: Deployed. Awaiting DFS confirmation that problem is solved. Post DSG10: Confirmation provided. To close in DSG11
DSG4 Deployment Action 9	DFS	Clarify plans for deploying a fix for CRO 793 (Unable to load clearance with NDBs from EDUU) and provide a deployment date	31/May/23	Fix will be deployed in the next major update of EDUU. Postponed to 2023
DSG7 Deployment Action 19	EANS	EANS to implement and deploy ED110B Change 1(2014) update.	01/Apr/23	End of Q1 2023
DSG7 Deployment Action 20	DFS	DFS to implement and deploy ED110B Change 1(2014) update.	31/Dec/23	
DSG7 Deployment Action 22	HungaroControl	HungaroControl to implement and deploy ED110B Change 1(2014) update.		Not planning to implement ED110B Change 1 as LOF/NAN is used with all neighbours and impact is low.
DSG7 Deployment Action 25	NATS	NATS to implement and deploy fix for CRO-555 issue	31/Jan/26	Delayed to 2026
DSG8 Deployment Action 1	NATS	NATS to implement and deploy ED110B Change 1(2014) update for EGPX to address CRO-1157.		DSG10: No target date available
DSG8 Deployment Action 2	NATS	Implementation of automated switchover between FANS-1/A and ATN for dual-stack aircraft to address CRO-1160.	30/Dec/24	

Action No	Who	Description	Due date	Status/Comments
DSG8 Deployment Action 3	IAA-Ireland	IAA to deploy Thales Topsy release B3.7 which solves the issue reported in CRO-1085	30/May/23	DSG10: Delayed COOPANS build 3.8 deployment delayed due to interactions with the regulator. Deployment date is to be confirmed.
DSG8 Deployment Action 4	ENAIRE	ENAIRE to deploy new SITA VGC to address CRO-744 and CRO948 issues	31/Dec/23	
DSG8 Deployment Action 5	ENAIRE	ENAIRE to update their system to support automatic 'CPDLC End' on Controller frequency release by voice to resolve CRO-1171	30/Nov/26	
DSG8 Deployment Action 7	ROMATSA	ROMATSA to deploy new SITA VGC to address CRO-744 and CRO948 issues	30/Sep/23	DSG10: One GS deployed, another four GSs expected to be deployed next (No date available). Due date moved to September 2023 (for DSG11)
DSG9 Deployment Action 8	AustroControl, CroatiaControl, IAA, LVF, NavP and Navair	COOPANS ANSP members to deploy Rel 3.8 to fix CRO-632 (TP4 extended numbering format)	31/Mar/23	
DSG10 Deployment Action 1	LPS-Slovakia	LPS to deploy fix for the issue of padding with unexpected space characters to uplink 'fixname' position parameter when less than 5 to address CRO-1364.	31/Mar/23	
DSG10 Deployment Action 3	NATS	UK NATS to deploy fixes to address CRO-853, CRO-1278 and CRO1053.		These changes are expected to take place when a new FDPS serving all UK airspace with a single Ground Facility Designator (likely to be EGII) will be deployed

DEPLOYMENT ACTIONS ON AIRCRAFT OEMs: 18 actions

Action No	Who	Description	Due date	Status/Comments
DSG6 Deployment Action 14	Boeing	Boeing to release BP V18 and service bulletin for 777 Aircraft with Honeywell AIMS2 (BP17.1, BP17.A, BP17A.1, BP V17C) to address CRO-785, CRO-966 and CRO-836.	29/Mar/24	DSG10: Delayed to Mar 2024. DSG9: Delayed to Jan 2023
DSG6 Deployment Action 15	Boeing	Boeing to release new Pegasus I FMC Software load BP V11 for 757/767 Aircraft. to address: CRO-417 Note: Fix for Pegasus II is already available	31/May/23	DSG10: Delayed to May 2023.
DSG6 Deployment Action 18	Airbus	Airbus to certify ATSU CSB10.2/CLR10.2 to address CRO-151, CRO-591, CRO-835, CRO-661 and CRO-1218.	31/Dec/23	DSG10: Certified for limited deployment - installed on a limited number of a/c to assess performance. Date for extended deployment is to be confirmed. Due date moved to end of 2023.
DSG7 Deployment Action 29	Airbus	Airbus to implement and deploy update to ACR to address CRO1110, CRO-151 and CRO-835		Date not currently available.

Action No	Who	Description	Due date	Status/Comments
DSG7 Deployment Action 30	Airbus	Airbus to certify FMS issue on A350 to address [CRO-1097] Affected FMS versions from S3 (A350 Entry Into Service) to S6A (last release certified) New FMS Version maybe either S6B or S7	31/Jul/24	DSG10: Target certification mid-2024, then deployment 2nd part of 2024.
DSG7 Deployment Action 34	Boeing	Boeing to certify and deploy BP7 for Honeywell fixes for the CMF on 787 airframes to address [CRO-966], [CRO-997], [CRO-1141], [CRO1296] and [CRO-836].		DSG10: Included BP7 in action text. Awaiting due date for BP7 deployment. No program commitment; Approval process ongoing. Action text updated to include additional PRs addressing CRO-1141, CRO-1296, CRO-836.
DSG7 Deployment Action 35	Boeing	Boeing to certify and deploy Honeywell NG-FMC fixes for the 747-8 airframe to address CRO-1266, CRO-1286, CRO-966 and CRO-997	29/Mar/24	DSG10: Brought forward to Mar 2024. From DSG9: Delayed to July 2024. Action text updated to include additional PRs to fix DEGREE Display Issue.
DSG7 Deployment Action 36	Gulfstream	Gulfstream to provide update to fix CRO-645 issue to all affected aircraft operators		DSG10: Still awaiting feedback from Gulfstream since DSG9.
DSG8 Deployment Action 9	Airbus	Airbus to provide certified release 8.0A3 to address CRO-737 and CRO-782 on the A220	29/Dec/23	
DSG8 Deployment Action 11	Boeing	Boeing to provide software update for Flight Management Function (FMF) BP5 on B787 aircraft to address CRO-1015.	31/May/24	DSG10: Delayed to May 2024.
DSG8 Deployment Action 12	Boeing	Boeing to provide U14.2 update to address CRO-1050 and CRO1181 issues	31/Dec/24	DSG10: Delayed to Dec 2024.
DSG8 Deployment Action 13	Embraer	Embraer to Update EJets E2 (aircraft family) with Primus EPIC Load 9.0 which includes EPIC CMF Block 3.4 to address CRO-777 and CRO-1173 Recommendation: Update to EPIC CMF Block 3.5 as this version has improved handoff logic (CRO-870)	30/Dec/22	DSG10: Still awaiting feedback from Embraer since DSG09 . HW has indicated that version 3.5 is in release process
DSG9 Deployment Action 1	Boeing	Boeing to certify and deploy fix for CMU-900 on Boeing 737, 757 and 767 aircraft to address CRO-834, CRO-912, CRO-487, CRO-589, CRO-881, CRO-801, CRO-1087, CRO-1016 and CRO-913	31/Jan/24	DSG10: Delayed to Dec 2023/Jan 2024 (757/767)
DSG9 Deployment Action 2	Boeing	Boeing to address CRO-1141 and CRO-1296 on B777X prior to Entry Into Service (EIS)	31/Jan/25	DSG10: Targeted for 2025
DSG9 Deployment Action 3	Boeing	Boeing to release BP19 and service bulletin for 777 Aircraft with Honeywell AIMS to address CRO-1141 and CRO-1296	30/Sep/24	DSG10: Delayed to Q3 2024, Reviewing list of must-fix items; SB available 1-2 months later.
DSG9 Deployment Action 4	Airbus	Airbus to provide update ATC System for A350 to address CRO-1228 and CRO-71.	04/Jan/27	DSG10: Delayed to 2027, Updated to address CRO-71 issue.
DSG9 Deployment Action 5	Airbus	Airbus to provide update ATSU CSB10.3 for A320 and CLR10.3 for A330/A340 to address CRO-1212, CRO-1228 and CRO-71.	31/Dec/24	DSG10: Certification target date is 31/Dec/2024. Updated to include CRO-71 issue.
DSG10 Deployment Action 11	Boeing	Boeing to provide fix for Collins Multi-mode Receiver (MMR) GLU925/GLU-2100 issue to address [CRO-786]		Date to be confirmed

DEPLOYMENT ACTIONS ON AVIONICS OEMs: 11 actions

Action No	Who	Description	Due date	Status/Comments
DSG6 Deployment Action 17	Collins	Collins to provide fix for CMU-900 on Boeing 737, 757 and 767 aircraft to address CRO-912, CRO-801 and CRO-834.	08/Jul/23	Further delayed to July 2023, Collins needs to confirm who (Collins or Boeing) will certify fix
DSG7 Deployment Action 26	Garmin	Garmin to implement update in Garmin Avionic platforms to fix DM99 retransmissions (CRO-1030).		DSG10: Garmin indicated fix will be included in ATS B2 Implementation around the 2026-2027 timeframe.
DSG7 Deployment Action 27	Honeywell	Honeywell to certify EPIC ATC BP? to address CRO-997 and CRO966		DSG10: No update is planned. Version to be confirmed. MKII+ CMU -525 development moved to DSG9-9 action to track different release timeline. Clarification of BP reference missing
DSG7 Deployment Action 32	Collins	Collins to provide fix for CMU-900 on Boeing 737, 757 and 767 aircraft to address CRO-487, CRO-589, CRO-881, CRO-1087, CRO-1016 and CRO-913	08/Jul/23	Delayed to July 2023
DSG7 Deployment Action 33	Collins	Collins to provide builds for the RIU/CMU-4000 family to fix CRO1012, CRO-912, CRO-1020, CRO-589, CRO-881, CRO-943, CRO1016 and CRO-913 issues.	08/Apr/23	Date brought forward to April 2023 for Final Black Label equipment
DSG8 Deployment Action 14	Collins	Collins to release guidance for operators to advise on the feature "Disable CPDLC" and how to reset it to Enabled to address CRO-969.		DSG10: Awaiting Collins feedback for date.
DSG9 Deployment Action 10	Honeywell	Honeywell to provide update NG-FMC BP5 to address CRO-1266 and CRO-1286 display issue with DEGREE parameter received in the UM190 FLY HEADING Messages and UM215 TURN Messages respectively		Date to be confirmed. Post DSG9 - updated to include fix for UM215 Messages (CRO-1286)
DSG9 Deployment Action 9	Honeywell	Honeywell to certify MKII+ CMU -525 to address CRO-966, CRO-997 and CRO-1141.	31/Dec/25	Delayed to 2024-2025. Adding CRO-966 and CRO-997 from Dep Action DSG7-27.
DSG10 Deployment Action 8	Collins	Collins to certify and deploy new CMU ATN database release based on v11 or a more recent version of NSAP Registry Doc.28 to address the CRO-900 issue.	31/Dec/24	
DSG10 Deployment Action 9	Garmin	Garmin to provide a fix to the issue of the Air/Ground Bit in AVLK downlink frames set to indicate Airborne while the aircraft is on the ground to address CRO-1151.	29/Sep/23	Expected Q3 2023 with additional airframes expected Q4 2024/Q1 2025
DSG10 Deployment Action 10	UASC	UASC to address CPDLC timer handling issue CRO-1164		

DEPLOYMENT ACTIONS ON CSPs: 7 actions

Action No	Who	Description	Due date	Status/Comments
DSG1 Deployment Action 3	SITA	Progressively deploy the fix for the unnecessary X25 clear request issue (CRO 744) to all SITA VGS and distribute the fix to its partners.	31/Dec/20	DSG10: Done for SITA and partner NAV Portugal. Pending for partners: ENAIRE and ROMATSA.
DSG6 Deployment Action 9	SITA	Complete deployment of new SW/HW on SITA VDL Ground Stations to address CRO-948		Addressed together with Dep Action DSG1-3
DSG7 Deployment Action 39	ARINC/Collins	ARINC/Collins to implement and deploy Ground Station (GS) Improvement (After HO uplink response, GS will wait for downlink before considering the link is established) for [CRO-877] (IDRP disconnect after two handoffs on ARINC network)	29/Sep/23	DSG10: Planned for September 2023
DSG10 Deployment Action 4	ARINC/Collins	ARINC/Collins to deploy the fix for the ISH Streaming issue after AGR switch-over and the fix for the high occurrence of AGR/GGR Resets to address CRO-1309 and CRO-1355.	30/Sep/23	Fix for ISH streaming maybe at the end of 2023
DSG10 Deployment Action 5	ARINC/Collins	ARINC/Collins to deploy Slow AGR switch-over fix to address CRO1308	30/Dec/23	
DSG10 Deployment Action 6	ARINC/Collins	ARINC/Collins to implement and deploy Multi-frequency management fixes to address the out-of-range GRAIHO issues; [CRO-771] and [CRO-1349].	31/Dec/23	
DSG10 Deployment Action 7	SITA	SITA to deploy new S/W Release on SITA VDL Ground Stations to address CRO-1003 and CRO-1042 issues.	30/Nov/23	

DEPLOYMENT ACTIONS/RECCOMENDATIONS ON OPERATORS (30/05/2023)

Action No	Who	Description	Status/Comments
DSG6 Deployment Action 1	Operators of aircraft equipped with Collins VDRs	Operators with Collins VDRs VHF-920, 2100 and 4000 to update Collins VDRs to fix the VDR deafness issue in accordance with EASA-SIB-202101 to address CRO-775 and CRO-914.	EASA SIB published
DSG6 Deployment Action 2	Operators of Boeing aircraft equipped with Honeywell RTA-44D VDRs	Operators with Honeywell RTA-44D VDRs on Boeing Aircraft to update Honeywell RTA-44D VDRs to fix the VDR Qc issue on Boeing Aircraft; for B717 Aircraft, update to PNs 064-50000-2032/998-2886-504 and 06450000-2001/998-2858-504 for all other Boeing Aircraft to address CRO776.	EASA SIB under development
DSG6 Deployment Action 3	Operators of Airbus aircraft equipped with Honeywell RTA-44D VDRs	Operators with Honeywell RTA-44D VDRs on Airbus Aircraft to update Honeywell RTA-44D VDRs to fix the VDR Qc issue on Airbus Aircraft; by updating to PN 064-50000-2052/998-2887-504 to address CRO-776.	EASA SIB under development
DSG6 Deployment Action 4	Operators of A320 Airbus aircraft using the ATSU CSB standard.	Operators using Airbus ATSU CSB Standard to update Airbus ATSU from CSB versions earlier than CSB8.3 FANS-B+ to a more recent CSB Standard to address CRO-779, CRO-414 and CRO-48.	Recommendation is for Operators to update to the most recent CSB Standard available, ATSU CSB9.4 version. Operators invited to contact Airbus for guidance on upgrading and information on available service bulletins.

Action No	Who	Description	Status/Comments
DSG6 Deployment Action 5	Operators of A380 Airbus aircraft	Operators of A380 aircraft to upgrade the ATC System to the CLA4.2 version to address CRO-499.	Action text updated to clarify ATC System and PRs addressed.
DSG6 Deployment Action 6	Operators of A350 Airbus aircraft	Operators of A350 aircraft to upgrade the ATC system to the CLV1.4 version to address CRO-499.	Action text updated to clarify ATC System and PRs addressed.
DSG6 Deployment Action 7	Operators of aircraft equipped with Honeywell Mark2+ CMU	Operators using the Honeywell Mark2+ CMU to update Honeywell Mark2+ CMU versions earlier than 998-6063-522 to 998-6063-523 to address CRO-783 and CRO-592.	Recommendation is for Operators to update to 998-6063-524 as this version will offer improved handoff logic (addressing also CRO-870)
DSG6 Deployment Action 8	Operators of aircraft equipped with Collins CMU-900	Operators using the Collins CMU-900 to update Collins CMU-900 versions earlier 815-5679-505 to 815-5679-505 or later when available to address CRO-301.	
DSG7 Deployment Action 37	Operators of B777 aircraft	Operators of B777 aircraft update their fleet to V17C Service Bulletin.	
DSG7 Deployment Action 38	Operators of A320 NEO aircraft	Operators of A320 NEO aircraft fitted with the CFM LEAP engine and Teledyne ACMS version D12 (PN: D12SAFC02C00000 or D12SAFC03CTFU01) to update the ACMS to software version D16 (PN D16SAFC03C00000) or later to fix the CRO-951 issue.	Airbus guidance TFU 31.36.00.087 addresses this issue. Operators invited to consult this document and contact Airbus for further information. Action text updated to specify concerned operators and equipment.
DSG8 Deployment Action 16	Operators of aircraft equipped with the Spectralux Dlink+ Mod 5	ON HOLD - TO BE REVISITED IN DSG11 (OCTOBER 2023) Operators of aircraft equipped with Spectralux Dlink+ with Mod 5 or earlier should update to Mod 6 or later to have improved PA-Rate performance and to fix CPDLC issues	25/05/23 LL meeting: Observed Mod 6 performance is not good. Decision to put Mod 6 in list of avionics with performance concerns. DSG10: SDA, the new owner of DLINK equipment, announced plans to develop Mod 7 to fix further issues, Action text updated to indicate post mod 6 development ongoing
DSG8 Deployment Action 17	Operators of aircraft equipped with UASC Avionics	Operators of aircraft equipped with UASC Avionics (UniLink UL-80X) to update to SCN 31.4 (SB Number:1080X.0X-23-3750) to have improved VDL Mode 2 handoff performance.	
DSG8 Deployment Action 18	Operators of Ejets E190 or E195 aircraft with EPIC avionics	Operators of Ejets (E190, E195) aircraft to update their fleets to Honeywell EPIC CMF 3.4, aircraft with EPIC FMS to install Load 25.9 and aircraft with EPIC NG FMS to install Load 27.4 to address CRO-777, CRO-48, CRO592 and CRO-225.	
DSG8 Deployment Action 19	Operators of B777 aircraft equipped with Collins Aerospace GLU-925/GLU-2100 MMR	Aircraft operators with B777 in their fleet are asked to make crews aware of the potential impact to datalink associated with a loss of GPS signal or GPS signal interference. Operators are invited to consult the Boeing Flight Ops Technical Bulletin, (FOTB) 777-47-R3, to understand the potential system impacts and flight deck effects associated with GPS interference. In the event that date and time shifts persist after a GPS signal loss or interference event, maintenance staff should apply Maintenance Tip 777MT-34-051 to restore proper functionality (applicable to Collins Aerospace GLU-925/GLU-2100 MMR).	DSG10: Text revised to provide reference to FOTB and Maintenance Tip. A fix is also under consideration for Collins GLU-xxx MMR..

Action No	Who	Description	Status/Comments
DSG8 Deployment Action 20	Operators of A31x or A32x aircraft	Operators of A31x or A32x aircraft series equipped with NorthropGrumman (formerly LITTON) ADIRU version 316 (PN:465020-0303-0316 or 465020-0304-0316) and THALES MMR (PN: TLS755-01-0101B or TLS755-01-0102A or TLS755-14-0101A or TLS755-01-0102A or TLS75514-0103A) to implement the means and/or actions described in Airbus TFU 34.36.31.003 to address the issue of the avionic clock date unexpectedly sifting backwards by 19.5 years (CRO-1132).	Airbus guidance TFU 34.36.31.003 addresses issue and proposes possible mitigation means and permanent corrective actions. Operators invited to consult TFU and contact Airbus for further information. Action text updated to specify concerned equipment.
DSG9 Deployment Action 11	Operators of C68A aircraft	Operators of C68A aircraft with Garmin Avionics system software version 4.5 to update to 4.8 by applying SB680A-34-10 for next generation hardware or CB680A-34-16 for legacy hardware to address CRO-947.	
DSG10 Deployment Action 12	Operators of A350 Airbus aircraft using the ACR standard	Operators of A350 aircraft with ACR S4 to upgrade PRODB database to RCF592292024300 for improve handoff to address CRO-953	
DSG10 Deployment Action 13	Operators of the B747-8 aircraft	Operators of the B747-8 aircraft with Collins Avionics to update to the -203 software by applying the Service Bulletin:SB-747-23-2618 to fix CRO-774, CRO-834, CRO-912, CRO-487, CRO-589, CRO-881, CRO-301, CRO1016 and CRO-913.	There is also a related Guidance, 747 FTD 2320002